

Assignment #5

Assigned Lecture #15

Due Lecture #17

Modify the program that you submitted for Assignment #4 to compute phase and impedance that would be measured by the relay. (Hint: You must handle the case when voltage is zero or when the phase is  $\pm 90$  degrees separately else you may get divide by zero errors)

Plot the phase in degrees and the absolute value of the impedance.